




Used Vehicle Inspection Report



Administrator: CIU		Inspection # 105059	
Customer Name: [REDACTED]		Policy / Contract # [REDACTED]	
[REDACTED] Tampa FL		Facility Phone: [REDACTED] Facility Contact: [REDACTED]	
<p>Reason For Inspection: Pre-purchase inspection -- Test drive the vehicle at least 10 miles. Be sure to take before and after ODOMETER pictures. Call CarInspector.US before you leave. Fax this worksheet ASAP. Upload Photos the evening of the inspection.</p> <p>*****CALL THE SHOP PRIOR TO GOING TO ENSURE THE VEHICLE IS READY FOR INSPECTION. CALL VERBAL TO CARINSPECTOR.US FROM THE SHOP 888-615-7555 ext 55. UPLOAD PICTURES TO WEBSITE (http://www.carinspector.us) THE EVENING OF THE INSPECTION. NO EXCEPTIONS!!!</p>			
Verbal Given To: NA		Inspected By: JD	
Date Inspected: 12-09-10		Time Inspected: 11:00	
Yr/Mk/Mdl: 2005 HUMMER LIMO		Mileage before test drive: 77417 after: 77422	
VIN: 5GRGN22U15H127715		Production Date: NA	
Engine Size: 6.0		Fuel Type: GAS	
Transmission Type: AUTO		Drive Type: RWD	
Oil Level: FULL		Oil Condition: GOOD	
Coolant Level: FULL		Coolant Condition: GOOD	
Trans Level: FULL		Trans Condition: GOOD	
Front Diff Level: NA		Front Diff Condition: NA	
Rear Diff Level: NA		Rear Diff Condition: NA	
Transfer Case Level: NA		Transfer Case Condition: NA	
Power Steering Level: FULL		Power Steering Condition: GOOD	
Brake Fluid Level: FULL		Brake Fluid Condition: GOOD	
Belts: GOOD	Hoses: GOOD	Overall Condition: VERY GOOD	Abuse? NO
		Mods? LEMO	Overheat? NO
Lack of Lube? NO	Previous or Current Collision? NO	Towing Type? CLASS 3	Tires Factory Size? NO
		Mechanical Failures? NO	Service History? NO
Service Stickers? NO	Prior Commercial Usage? LEMO	License Plate Info: 610ZXEU	Level of Teardown: FULLY ASSEMBLED
Date: _____ Inspector Signature: _____			

There is existing damage on the vehicle as notated on diagrams to the right. Legend for damage is below:

B - Bent	M - Missing
BB - Buffer Burn	P- Pitted
BR - Broken	PC - Paint chip
C - Cut	R- Rubbed
CR - Cracked	RU - Rusted
D - Dented	S - Scratched
F - Faded	SL - Soiled
FF - Foreign Fluid	SS - Surface Scratch
G - Gouged	ST - Stained
L - Loose	T - Torn



BODY ITEM	OK	DESCRIPTION See legend on pg 1	REPAIR	REPLACE	BODY ITEM	OK	DESCRIPTION See legend on pg 1	REPAIR	REPLACE
Windshield	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Tail Lamps	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Hood	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Parking Lamps	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Grille	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Interior Lights	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Front Bumper	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Head Lamps	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Rear Bumper	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Carpet	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Right Fender	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Upholstery	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Right Front Door	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Headliner	<input checked="" type="checkbox"/>	Missing right sunvisor	<input type="checkbox"/>	<input type="checkbox"/>
Right Rear Door	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Dash	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Right 1/4 Panel	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Front Seats	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Right Rocker Panel	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Rear Seats	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Left Fender	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	3 rd Seat	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Left Front Door	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Seat Belts	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Left Rear Door	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Keyless Entry	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Left 1/4 Panel	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Anti-Theft	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Left Rocker Panel	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Radio Operation	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Roof	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Power Windows	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Deck Lid	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Power Locks	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Rear Glass	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Power Mirrors	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Frame/Unibody	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>	Horn	<input checked="" type="checkbox"/>		<input type="checkbox"/>	<input type="checkbox"/>
Tires: Front-Left	<input checked="" type="checkbox"/>	7	/32	<input type="checkbox"/>	<input type="checkbox"/>	Hood Release	<input checked="" type="checkbox"/>		<input type="checkbox"/>
Front-Right	<input checked="" type="checkbox"/>	7	/32	<input type="checkbox"/>	<input type="checkbox"/>	Trunk Release	<input checked="" type="checkbox"/>		<input type="checkbox"/>
Rear-Left	<input checked="" type="checkbox"/>	7	/32	<input type="checkbox"/>	<input type="checkbox"/>	Fuel Door Release	<input checked="" type="checkbox"/>		<input type="checkbox"/>
Rear-Right	<input checked="" type="checkbox"/>	7	/32	<input type="checkbox"/>	<input type="checkbox"/>	Owners Manual	<input checked="" type="checkbox"/>		<input type="checkbox"/>
Spare	<input checked="" type="checkbox"/>	8	/32	<input type="checkbox"/>	<input type="checkbox"/>	Jack/Tire Tools	<input checked="" type="checkbox"/>		<input type="checkbox"/>

MECHANICAL ITEMS	Good	Fair	Poor	Yes	No	N/A	Comments
Engine:							
Evidence of Leaks				<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
Abnormal Noises				<input type="checkbox"/>	<input checked="" type="checkbox"/>		
Transmission:							
Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			<input type="checkbox"/>	
Evidence of Leaks				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Abnormal Noises				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Steering:							
Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			<input type="checkbox"/>	
Evidence of Leaks				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Abnormal Noises				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Brakes:							
Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			<input type="checkbox"/>	
Evidence of Leaks				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Abnormal Noises				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Air Conditioning							
Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			<input type="checkbox"/>	
Evidence of Leaks				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Abnormal Noises				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Drivetrain:							
Performance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			<input type="checkbox"/>	
Evidence of Leaks				<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Abnormal Noises				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

All of our inspections are based on a physical description of what is seen and heard through the eyes and ears of our inspectors. We do not advise on the value of the vehicle or authenticate its origin. We do not advise as to purchase or decline any vehicle we inspect. This inspection was performed by CarInspector.US (CIU) in a professional manner, without the use of diagnostic tools or equipment. Accordingly, CIU is not liable for any hidden, latent, or undetected conditions or defects on the vehicle or any of its component parts. This inspection does not create or result in any representations or warranties by CIU with respect to the safety, condition, or operation of the vehicle or any of its parts. CIU expressly disclaims any such representation and warranties. We do not verify if a vehicle is emission compliant. We cannot advise as to how long the vehicle will perform properly. We are not responsible for any problems that can occur after an inspection is completed. CIU guarantees each inspection to be accurate at the time the vehicle is inspected. Physical and mechanical damage can occur between the time a vehicle is inspected and when the vehicle is actually purchased and CIU cannot be held responsible for those occurrences should they ever happen. This inspection does not create or result in any representations or warranties by CIU with respect to safety, condition, or operation of the vehicle or any of its parts. CIU expressly disclaims any such representations and warranties. Any guarantees or warranties implied or not on any vehicle inspected by CIU is strictly with the seller of that vehicle.














MULTI-STATE VEHICLE HISTORY REPORT








VIN 5GRGN22U15H127715
YEAR 2005 MAKE Hummer

This data was originally accessed on 2010-12-08 16:18:04.392 EST at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)



A "Brand" defines the status of a vehicle, such as Theft, Flood, Salvage or Rebuilt. A brand is carried with the title as the vehicle travels from state to state. There are over 250 brands recognized by NMVTIS that can be categorized by type.

BRAND CATEGORY	NMVTIS SEARCH RESULT
Total Loss	 No Brand Reported
Salvage	 No Brand Reported
Disclosed Damage	 No Brand Reported
Bond	 No Brand Reported
Flood	 No Brand Reported
CARS/Cash for Clunkers	 No Brand Reported
Gray Market	 No Brand Reported
Junk	 No Brand Reported
Manufacturer Brand	 No Brand Reported
New/Re-Issued VIN	 No Brand Reported
Odometer	 No Brand Reported

Rebuilt/Repaired/Reconstructed	 No Brand Reported
Dismantled	 No Brand Reported
Rental/Taxi/Police	 No Brand Reported
Agricultural/Logging Vehicle	 No Brand Reported
Title Copy	 No Brand Reported
Antique/Classic	 No Brand Reported
Undisclosed Lien	 No Brand Reported

**TITLE INFORMATION****Current Title Information**

State	VIN	Issue Date	Odometer
Florida	5GRGN22U15H127715	06/24/2009	000073300 Miles

Historical Title Information

State	VIN	Issue Date	Odometer
Florida	5GRGN22U15H127715	06/29/2005	000000006 Miles
Florida	5GRGN22U15H127715	10/25/2007	000066025 Miles

**STATE CONTACT INFORMATION**

If you need more information, please contact the State of Florida by visiting <http://www.flhsmv.gov/data/othercomp.html>.

**JUNK & SALVAGE INFORMATION**

Reporting Occurrence	Reporting Entity Information	Date Obtained	Vehicle Intended for Export?	Vehicle Disposition
----------------------	------------------------------	---------------	------------------------------	---------------------

No Junk/Salvage Reportings Found

**INSURANCE INFORMATION**

Reporting Occurrence	Reporting Entity Information	Date of Total Loss Declaration or Date Total Loss Claim Paid
----------------------	------------------------------	--

No Total Loss Reportings Found



DETAILED VEHICLE INFORMATION

Standard Data

Body Type	4D SUT	Manufactured	United States
Drive Line	All Wheel	Engine Type	6.0L V8 SFI
Fuel Type	Gas	Make	Hummer
Model	H2	Corporation	GM
Model Year	2005	Production Seq. No.	127715
Vehicle Class	4D SUT		

Drivetrain - Axle

Differential	Locking, rear	Ratio	4.1
---------------------	---------------	--------------	-----

Safety

Child Safety Features	Locks, rear doors	Airbag - Occupant Sensor	Included
Airbag - Front Passenger	Included	Lap Belt - Middle Rear	Included
Remote Keyless Entry	Panic Button	3-Pt Seat Blts - Outer Rr	2nd row
Lights	Daytime running lights	3-Point Seat Belts - Fr	Included
Airbag - Driver	Included	Traction Control	Single Wheel

Suspension

Stabilizer Bar	Front & rear	Springs	5-link coil
-----------------------	--------------	----------------	-------------

Warranty

Basic	3-year/36,000-mile, Limited
--------------	-----------------------------

NOTE: Detailed Vehicle Information is obtained by decoding the Vehicle Identification Number (VIN). The equipment currently installed in the vehicle may differ from the equipment listed in the report (i.e. the possibility exists that the vehicle may have been modified or rebuilt).

NMVTIS CONSUMER ACCESS PRODUCT DISCLAIMER

NMVTIS Consumer Access Product Disclaimer

- The National Motor Vehicle Title Information System (NMTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMTIS is intended to serve as a reliable source of title and [brand](#) history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.
- All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMTIS. However, NMTIS does not contain information on all motor vehicles in the United States because [some states](#) are not yet providing their vehicle data to the system. Currently, the data provided to NMTIS by states is provided in a variety of time frames; while some states report and update NMTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.
- Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."
- Before making a decision to purchase a vehicle, consumers may wish to obtain an independent vehicle inspection, a NMTIS Vehicle History Report, and consult other available vehicle information resources.
- The information in NMTIS **INCLUDES**:
 - Information from [participating](#) state motor vehicle titling agencies.
 - Information on automobiles, buses, trucks, motorcycles, recreational vehicles, motor homes, and tractors. NMTIS may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time.
 - Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.
 - Most recent odometer reading in the state's title record.
 - Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.
 - Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.
- Consumers are advised to visit www.vehiclehistory.gov for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies.



ADD Consumer Access Disclaimer

- Auto Data Direct, Inc. is a "read-only portal" of data stored in the NMTIS databases. Data is passed directly from [AAMVA](#) to the client through the ADD interface, which has been tested and approved by AAMVA. ADD does not enter the information found on a NMTIS record, nor is it responsible for the accuracy or verification of the information found therein. The motor vehicle records accessed by ADD clients are recorded by participating states and are current with those entities at the time of access through the ADD portal.
-





















2AND321

ODOMETER: 77417 MI





MFD BY AM GENERAL LLC FOR GENERAL MOTORS CORP. 04/05

GWR

GAWR FRT

GAWR RR

3901KG(8600LB)

1814KG(4000LB)

2298KG(5080LB)

THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR
VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF
MANUFACTURE SHOWN ABOVE.

5GRGN22U15H127715

TYPE: M.P.V.

MODEL: N25736

NPDC TIRE SIZE

FRT LT315/70R17D

RR LT315/70R17D

SPA LT315/70R17D

RIM

17X8.5J

17X8.5J


17X8.5J

COLD TIRE PRESSURE

260KPA(37PSI)

260KPA(37PSI)

310KPA(45PSI)

SEE OWNER'S MANUAL  FOR MORE INFORMATION.











A close-up photograph of a black satellite dish mounted on the roof of a dark-colored car. The dish is sleek and aerodynamic. The background shows a line of green trees under a clear blue sky. The car's body is dark and reflective.

TRACVISION
SATELLITE TV BY BMW



















